

FABRIC CARE GUIDE

Theorem Power Lift Recliners has **THREE** different fabrics in the range.

Two models, the **MERCER** and **SEAGROVE**, have a PU (polyurethane) face and a Polyester backing.

The **EALING**, **SOMERSET**, and **ABINGDON** are a leather match - 100% leather is used on all the touch-point areas, such as seat, back, arms, and leg rest. Then matching PU is used elsewhere.

All of Theorem fabric upholstered chairs are 100% **POLYESTER**.

Theorem Power Lift Recliners uses several different weaves and surface finishes to create diversity in the range, but the yarn that is used is always the same.

The polyester fabric has an inherent stain resistant quality to it and the majority of stains can be removed by using a clean damp cloth. A fabric protector can be used on the chairs, but Theorem recommends testing on a hidden area first.

The leather chair needs to be treated and cleaned as any other leather chair, with a specific leather cleaner.

TWO-YEAR FABRIC WARRANTY

Theorem Power Lift Recliners guarantees to replace any fabric that is found to be faulty as a result of manufacturing defect and which has been used in accordance with our manufacturer performance ratings and care instructions. An evaluation of fabric related issues must be conducted before confirmation of warranty coverage can be verified. Theorem recommends stain resistant treatment before use.

CONSUMER WARRANTY AGAINST DEFECTS: Theorem does not warrant against excessive or incorrect use, modification or any situation that could not be deemed as fair wear and tear. This is a back to base warranty and does not cover freight costs pertaining to the return of any items under warranty. Theorem acknowledges and conforms to all ACCC guidelines around consumer rights. Theorem will not warrant the safety and or correct functioning of products where any original components have been changed or modified by non-Theorem approved and trained service & maintenance staff or external providers.

Furthermore, safety is not guaranteed where components have been replaced with non-original Theorem approved parts. If any faults are detected upon receipt of this product please contact Theorem Power Lift Recliners. Any faults that are detected during normal use should be reported to Theorem immediately to determine if warranty conditions apply and if so, the necessary repair or replacement work to be completed.

Please contact your Theorem stockist for further information.